## UNCLASSIFIED

# AD NUMBER ADA800704 CLASSIFICATION CHANGES TO: unclassified FROM: restricted LIMITATION CHANGES

## TO:

Approved for public release; distribution is unlimited.

# FROM:

Distribution authorized to DoD only; Foreign Government Information; OCT 1946. Other requests shall be referred to British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.

# **AUTHORITY**

DSTL, DSIR 23/15899, 19 Jul 2009; DSTL, DSIR 23/15899, 19 Jul 2009

# Reproduction Quality Notice

This document is part of the Air Technical Index [ATI] collection. The ATI collection is over 50 years old and was imaged from roll film. The collection has deteriorated over time and is in poor condition. DTIC has reproduced the best available copy utilizing the most current imaging technology. ATI documents that are partially legible have been included in the DTIC collection due to their historical value.

If you are dissatisfied with this document, please feel free to contact our Directorate of User Services at [703] 767-9066/9068 or DSN 427-9066/9068.

# Do Not Return This Document To DTIC

# Reproduced by AIR DOCUMENTS DIVISION



HEADQUARTERS AIR MATERIEL COMMAND
WRIGHT FIELD, DAYTON, OHIO

# U.S. GOVERNMENT

IS ABSOLVED

FROM ANY LITIGATION WHICH MAY

ENSUE FROM THE CONTRACTORS IN-

FRINGING ON THE FOREIGN PATENT

RIGHTS WHICH MAY BE INVOLVED.

# REEL-CASSING

9327

# RESTRICTED

RES

SUITABLE.

BRITISH REST CTED Equals UNITED STATES RESTRICTED

·BRITISHYU.S. KLUTRICTED

Class Number 533,691,11

Technical Note No. Aero 1819a

October, 1946

## BOYAL AIRCRAFT ESTABLISHMENT, FAZISBOROUGH

Systematic Measurements of Downwash Behind Sweptback Wings, by Hans Trienes A.I.T.H.B. Report 45/8.

Abstract

ATI No.9327

Air Controverts Division, T-2
AirC, Wright Fold
Microfilm Re
2.27

by
H.H. Lyon, M.A.

ADDETIDUM

In the abstract of A.I.T.H.B \* report 45/8 given in Technical Note No. Aero 1819 only the rate of change of downwash with wing incidence was shown in the diagrams. For a given change in incidence the reduction in CL due to sweepback causes a loss of downwash, apart from any change in lift distribution.

The attached Table II gives the lift curve slope and the rate of change of tailplane incidence with  $C_{\rm L}$ , as well as the rate of change of downwash with wing incidence, for all the wings and test conditions. The slopes are measured over a moderate incidence range. At large incidences the Reynolds number of the tests  $(0.4 \times 10^5)$  is two small to give useful results.

The effect of the change of lift distribution due to sweepback is to reduce downwash and increase tailplane incidence  $a_{\tilde{l}\tilde{l}}$  for a given change in  $C_{L_0}$ . Thus, on both tapered and constant chord wings,  $d_{R_0}/dC_L$ , increases with sweepback.

## Circulation:

D.S.R.(A)
A.D.i.R.D.(Ros)
A.D.S.R.(Records)
D...R.D.
P.D.T.D.
R.T.P(TI.B)
D.D.i.R.D.(Serv.)
D.D.i.R.D.(Perf.)
i.R.C.(S. & C.)
36

Director
D.D.R.i.E.
Library
S.M.E.
Mero (1)
Mr.Hartshorn
Aero T/i., P,
F, F/J, S, H,
E, W.

\* Lerodynamic Institute, Technical High 🛭

unawick.

TABLE II - dOy/dx of the wing alone (from FB.1629, UM.2069, UM.2103) and of the arrangement tested 'without tail plane' in the downwash investigation, also the factors dOy/dx and dyy/dO, for all wings and test conditions.

da da wing	7.52.52 5.52.52 5.52.52 5.52.52 5.52.52 5.52.52
da da wing alone	3.96 3.38 3.38 3.56 5.55 5.55
Ving	#Iliptic wing 19/00/5 06/00/5 06/00/5 10/15/5 10/15/5 10/15/5 06/15/5 06/15/5 06/15/5 06/15/5 06/15/5

		-	10	CORR		-	•					
		02/45/5		H G		-	67160	-	-			
	1			da da		0	0.4.0	0.47	0.39	0.42	0.40	0.37
	116/6	10/45/5		Hup		0.180	0,195	0.201	0,225	0.210	0.210	0.225
	1	4	36.	Ħ.	CLC.	0.40	0.35	0.33	0.25	200	30	0.0
	30/5	19/39/5		S. L.		0.138	6910	9910	0.108	0.188	201	27.0
1	10/	-	do.	do da		0.50	0.41	0.40	36.0	35	30	
	0/15/5		daH	Ş	1	-	0,143		_		_	
	10		dô <sub>H</sub>	da			C 4.0	-				
	10/-30/5		Hzp	dC <sub>L</sub>		_	151.0			_		
	707		dS <sub>H</sub>			52	67.0	0.38	7770	0.43	0.00	
2/00/5	C 100 bo	-	H	Q <sub>T</sub>	1	0,113	0.127	0.143	0.129	0.158	00.1.00	
0	5	350	등		1	0.58	0.53	24.0	0.52	0.1.0	1	
5/00/5		don		7	76000	0.129	0.139	0.158	2777	9910		
90		dôn	H N		0.56	0.52	0.48	14.0	0.45	0.38		
Elliptic 10/00/5		dr.H				-	141		****			
		Hop	Ġ,	1	19.0	0.47	24.0	0.40	0.39	0.33		
	Ing	Hap	dO <sub>T</sub>	0000	7600	0 1 20	0.137	0.129	0.137	0.144		
	1 25	F F					0.46		0,46	C+-0		
Tail plane	TOTA	I o		0.0			<b>7.°</b> 0	2.5	7-7-	+•		
Tail	1	2 12		0.5	1.0	1.5	1	1	7	-		
	16	d	-	TO S	5	-		_	-		ı	

OH = downwash angle

Wing Homenolature: 02/455 = Taper ratio 0.2, sweepback 450, Aspect ratio 5 10/-30/5 = Taper ratio 1.0, Sweepback  $-30^\circ$ , Aspect ratio 5  $^{\rm G}{\rm H}$  = angle of incidence at the tail =  $^{\rm G}{+}^{\rm T}{\rm P}$   $^{-}{\rm C}_{\rm H}$ 

# REEL-C 359 A.T.I.

9327

The State of the Line of the Paris

TITLE: System	ATI- 9327										
	(None)										
AUTHOR(S) ORIG. AGENC	ORIG. AGENCY NO. Aero-1819a										
PUBLISHED BY	PUBLISHING AGENCY NO. (Same)										
Oct 46											
ABSTRACT:		•									
Table is presented which gives lift curve slope, rate of change of tailplane incidence with lift coefficient, and rate of change of downwash with wing incidence, for all wings and under all test conditions. Slopes are measured over a moderate incidence range. Change of lift distribution caused by sweepback reduces downwash and increases tailplane incidence for a given change in lift coefficient.											
DISTRIBUTION: Copies of this report obtainable from CADO.											
DIVISION: Aero SECTION: Wing				SUBJECT HEADINGS: Wings - Aerodynamics (99150); Wings, Swept-back - Downwash (99305.65)							
ATI SHEET NO	.: R-2-6-17	7									
Central Wright-Patterson	Air Documents Air Force Base		AIR	TECHNICAL I							

TITLE: System	* 1	ATI- 9327									
AUTHOR(S)	ORIG. AGENCY NO. Aero-1819a										
PUBLISHED BY	PUBLISHING AGENCY NO. (Same)										
Oct 46	poc. class. Restr.	COUNTRY Gt. Brit.	Englis		table						
ABSTRACT:											
Table is presented which gives lift curve slope, rate of change of lailplane incidence with lift coefficient, and rate of change of downwash with wing incidence, for all wings and under all test conditions. Slopes are measured over a moderate incidence range. Change of lift distribution caused by sweepback reduces downwash and tncreases tailplane incidence for a given change in lift coefficient.											
DISTRIBUTION: Copies of this report obtainable from CADO.											
	DIVISION: Aerodynamics (2) SECTION: Wings and Airfoils (6) SECTION: Wings and Airfoils (6) Swepl-back - Downwash (99305.65)										
ATI SHEET NO	.: R-2-6-17	7									
Central Wright-Patterson	Air Documents Air Farca Base		AIR	TECHNICAL IN	DEX						

# **C** EO 10501 dd **5 NOV** 1953

ed From Chora Wast C



Tonormal of the Engine (dst) Parking Service (dst) Parking White Service (base) White Service (base) White Service (base) Parking (base)

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: ADA800704

Date of Search: 19 Oct 2009

Record Summary: DSIR 23/15899

Title: Downwash behind sweptback wings (RAE TN AERO 1819a)

Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department): ARC 10062

Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967. The document has been released under the 30 year rule. (The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as <u>UNLIMITED</u>.